

Spare Parts: School Pattern - Stuffing Box Assembly - Bib/Pillar - 1/2 Turn Ceramic Disc

School Pattern Bib/Pillar Stuffing Box Assembly - 1/2 Turn Ceramic Disc



PRODUCT CODE

VPQ380


VPQ BIB/PIL SBA



Due to ongoing Research and Development, specifications may change without notice.
Component specifications may change on some export models.
Refer to warranty statement for warranty details - www.enware.com.au/warranty.

TECHNICAL DATA

Finish	Chrome
Valve Type	Ceramic Disc
Maximum Ceramic Disk Operating Temperature	85°C
Maximum Jumper Valve Working Temperature	95°C
Maximum Working Pressure	500kPa



SPARE PARTS

PZQ380	Spare Parts: Plaza - Bib/Pillar Stuffing Box Assembly - 1/2 Turn Ceramic Disc
VPQ380	Spare Parts: School Pattern - Stuffing Box Assembly - Bib/Pillar - 1/2 Turn Ceramic Disc

Version 02 July 2023

1300 369 273 | info@enware.com.au | enware.com.au

ENWARE
A WATTS Brand